

GOVERNMENT OF TELANGANA STATE
ROADS AND BUILDINGS DEPARTMENT

From:

Sri G Vasant Naik,
B.E.,M.B.A,
Executive Engineer,
District (R&B) Officer,
Yadadri Bhongir.

To: ✓

The Principal,
ZEE High School,
(Unit of Life Kare Educational Society),
C.B.S.E Affiliation No:3630110,
Door No:4-136, Sy No:194-196/A,
Deshmukhi Village,
Pochampally Mandal,
Yadadri Bhongir District.

Lr. No.DB/D1/ 2017-18/ 169/1

28/4/17
dt. 27.04.2017

Sir,

Sub: - (R&B) Department –Zee High School CBSE Affiliation No:3630110 Unit of Life Kare Educational Society, Deshmukhi Village, Pochampally Mandal, Yadadri Bhongir District – Soundness certificate- Reg.

Ref: - 1) Your ltr Ref No:MLZHS/2017/04/18 dt:18.04.2017.

2) DyEE(R&B) Bhongir Lr No:DyEE/Bhongir/Soundness Certificate/2017-18/2certificates dt:26.04.2017

Adverting to the subject cited, I am to inform that the above said school building was inspected by the Deputy Executive Engineer (R&B) subdivision Bhongir on 26.04.2017 and found that the existing building is safe and structurally sound.

Therefore, structural soundness certificate is hereby issued for the building.

Yours faithfully

bs
Executive Engineer,
District (R&B) Officer,
Yadadri Bhongir.

27/4

STRUCTURAL SOUNDNESS CERTIFICATE
TO WHOME SO EVER IT MAY CONCERN

Certified that the structure of the building Zee High School, CBSE
Affiliation No: 3630110 (Unit of Life kare Education Society) DNo: 4-136,
Sy No: 194-196/A Near Anmagal, Hayatnagar Vill Deshmukhi, Mandal
Pochampally, Dist Yadadri Bhongir is inspected on 26.04.2017 and found to
be safe and structurally sound.

1000-200
26/4/17
Dyoe/B

BS-1-280417
Executive Engineer
(R&B) District Officer
Division, Bhongir